L Number	Hits	Search Text	DB	Time stamp
1	2	5649357.pn.	USPAT;	2004/04/26
		·	US-PGPUB;	15:30
			EPO; JPO;	
			DERWENT;	
		•	IBM_TDB	
2	9	("3997956" "3999270" "4020540"	USPAT	2004/04/26
		"4047294" "4048711" "4109370"		15:27
		"4384402" "4820184" "4825530").PN.		
3	11	("3758935" "3803695" "3845535"	USPAT	2004/04/26
		"3859724" "3866295" "3866297"		15:28
		"3972101" "4110896" "4148138"		
		"4332083" "4349944").PN.		
4	54	tool and edge near connection and pcb	USPAT;	2004/04/26
			US-PGPUB;	15:37
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
5	0	tool and edge near connection and pcb and	USPAT;	2004/04/26
		29/\$.ccls. and (439/62, 439/493 , 439/67 ,	US-PGPUB;	15:33
		439/77).ccls.	EPO; JPO;	
			DERWENT:	
			IBM_TDB	
6	1	tool and edge near connection and pcb and	USPAT;	2004/04/26
		(439/62, 439/493 , 439/67 , 439/77).ccls.	US-PGPUB;	15:35
		, , , , , , , , , , , , , , , , , , , ,	EPO; JPO;	
			DERWENT;	
			IBM TDB	
7	2	camnhung near tran.inv.	USPAT;	2004/04/26
			US-PGPUB;	15:35
			EPO; JPO;	
			DERWENT;	
			IBM TDB	
8	0	tool and edge near connection and pcb and	USPAT;	2004/04/26
_		29/\$.ccls.	US-PGPUB:	15:38
		20,4100101	EPO; JPO;	10100
			DERWENT;	
			IBM TDB	
		1	: DIVI (UD	I .

Fiostission of allege

	Title	Current OR
1	Wire insertion tool	29/566.4
2	Terminating apparatus for flat cable	29/749
3	Connector assembly tool	29/749
4	Cable connecting station	29/566.3
5	Tool for trimming wires and inserting the trimmed wires into a connector	29/749
6	PRE-LOADED ELECTRICAL CONNECTORS, ASSEMBLY APPARATUS AND METHOD	29/566.3
7	Apparatus for connecting conductors to which are back to back	29/566.3
8	METHOD AND APPARATUS FOR MANUFACTURING ELECTRICAL HARNESSES	29/867
9	APPARATUS FOR CONNECTING CONDUCTORS TO CONTACT TERMINALS IN AN ELECTRICAL CONNECTOR	29/56.6
10	APPARATUS FOR INSTALLING AN ELECTRICAL CONNECTOR ON CONDUCTORS INTERMEDIATE THE ENDS THEREOF	29/749
11	APPARATUS FOR SECURING WIRES TO TERMINALS IN CONNECTORS	29/566.4